



IRC CHI - SER

www.cno.cl +56 9 98217776 achavez@cno.cl



0.8 0.9 1.0 1.1 1.2

BOAT:

Name: RUCAPELEY II
 Sail Number: CHI2
 Design: BAVARIA 39 1.85
 Cert No.: 48200
 Crew No.: 10 (850 kg)

TCC: 0.981
Year: 2022

SER LIMITED VALIDITY

Valid from: 03 Dec 22
 Expires: 04 Dec 22
 No Spinnaker TCC: 0.975

SINGLE EVENT RATING

NOTES:

Issue: CERTIFICAT SER : Regata Patagonia Yacht Charter - Puerto Montt 2022

STD Hull data

HULL		OVERHANGS		HULL, KEEL & ENGINE NOTES	
LH	11.93	BO	0.46	Series Date: 2005, Age Date: 2006	
LWP	10.63	x	0.00	Internal ballast: 0 kg	
Hull Beam:	3.97	h	0.00	Weight includes batteries/cushions	
Boat Weight:	8500	SO	0.84	No variable/moveable ballast carried	
DLR	214	y	0.25	Low vcg iron keel. No wing keel	
Draft:	1.85			Inboard engine : Weight 220 kg	
Bulb weight:	N/A			3 blade folding propeller	
				Hull Factor: 7.3	

RIG & MAINSAIL		MIZZEN		HEADSAIL		FLYING HEADSAIL		SPINNAKER	
P	14.15	PY	--	HSA	40.04	FSA	--	SPA	105.00
E	4.90	EY	--	HLUmax	14.24	FLU	--	SLU	--
J	4.35	LLY	--	HLU	14.24	FLP	--	SLE	--
FL	15.20	LPY	--	HLP	5.61	FUW	--	SFL	--
MUW	1.08	ID#		HUW	0.70	FTW	--	SHW	--
MTW	1.86			HTW	1.40	FHW	--	ID#	--
MHW	3.19			HHW	2.81	FSFL	--	SPL	--
ID#				ID#		FSHW	--	STL	4.45
						ID#			

RIG & SAIL NOTES

Bermudian Sloop, Rig Factor: 1.008
 Max number of spinnakers carried: 3
 Max number of flying headsails carried: 0
 Bowsprit only/deck tack point, NO spinnaker poles
 NO whisker pole set to leeward
 Multiple headsails permitted (Furler LP<1.3*J)

Aluminium Mast, Wire standing rigging
 Mast foot/forestay not adjusted while racing
 2 Spreader/Jumper (sets)
 1 Aft Rigging (Sets)
 Manual power only for running rigging

OWNER

LEPELEY, Joaquin
 San Sebastian 2953, depto 101, Las Condes
 SANTIAGO,
 CHILE

STABILITY & SAFETY

STIX: 0
 AVS: 0
 SSS: 42
 ISO/IRC Design Category: N/A
 World Sailing Plan Review: N/A
 World Sailing OSR compliant lifelines fitted

IRC Rule 8.8 Change of ownership and/or changes in sail number will automatically invalidate the rating certificate.
 IRC Rule 8.9 Physical changes which might affect the performance of the boat shall be declared and may invalidate the rating certificate
 IRC Rule 13.3 The accuracy of the measurements supplied shall be the owner's responsibility.
 IRC Rule 13.4 It is a breach of the Rules of IRC for any owner or individual to intentionally supply false information.