



YACHT CLUB DE CHILE

**IRC CHI**

www.yachtclubdechile.cl +569 98217776 achavez@ycch.cl



**BARCO:**

Nombre: BRAMADOR  
 N° de vela: CHI6415  
 Tipo: FIRST 36.7 2.20  
 No. de Cert.: 39644  
 No. de tripulantes: 8 (680 kg)

**TCC: 1.016**

**Year: 2025**

**TCC SIN SPINNAKER: 1.005**

**CERTIFICADO ESTANDAR**

Válido del: 22 Jan 26 11:55:02

Hasta el: 31 May 26

**RENOVACION**

Weight ORCi -2% / Lwp, Rig measured: IRC/Chile 01.0002018

**CASCO**

LH 10.68  
 LWP 9.19  
 Manga maxima: 3.45  
 Peso: 5499  
 DLR 221  
 Calado : 2.21  
 Peso del bulbo: N/A

**LANZAMIENTOS**

BO 0.41  
 x 0.08  
 h 0.06  
 SO 1.08  
 y 0.19

**NOTAS - CASCO, QUILLA Y MOTOR**

Fecha de la serie: 2001, Fecha de botadura: 2006  
 lingotes: 0 kg  
 Peso con colchonetas y baterias  
 No lastres móviles  
 Alerón de plomo con bulbo de plomo: quilla única.  
 Motor intra borda : Peso 150 kg  
 Helice 2 palas plegables / orientables  
 Factor de casco calculado: 8.3

**APAREJO**

P 13.89  
 E 4.93  
 J 4.02  
 FL 14.63  
 MUW 0.91  
 MTW 1.80  
 MHW 3.09  
 ID#

**SEGUNDO MASTIL**

PY --  
 EY --  
 LLY --  
 LPY --  
 ID#

**VELA DE PROA**

Max No. 2  
 HSA 44.58  
 HLUmax 14.38  
 HLU 14.38  
 HLP 6.16  
 HUW 0.87  
 HTW 1.57  
 HHW 3.07  
 ID#

**FLYING HEADSAIL**

Max No. 0  
 FSA 0.00  
 FLU --  
 FLP --  
 FUW --  
 FTW --  
 FHW --  
 FSFL --  
 FSHW --  
 ID#  
 STLFHmax --

**SPINNAKER**

Max No. 2  
 SPA 85.84  
 SLU 13.92  
 SLE 13.92  
 SFL 7.23  
 SHW 7.48  
 ID#  
 SPL 4.03  
 STL 4.03

**NOTAS - APAREJO Y VELA**

Marconi Sloop, Factor de aparejo calculado: 1.005  
 Mástil de aluminio, jarcia de cable  
 2 Cruzetas y/o Violines (parejas)  
 1 Aparejo de popa (parejas)  
 Energía manual para ajustar las jarcias de labor  
 El pie de mástil/estay de proa no ajustables en regata

NO tangon(es) para velas de proa a satavento  
 Tangon(es) para spi Y botalon

**PROPRIETARIO**

LEDEZMA, Rodolfo  
 VINA DEL MAR,  
 CHILE

**ESTABILIDAD Y SEGURIDAD**

STIX: 34  
 AVS: 126  
 SSS: 28

Design Category: A  
 World Sailing Plan Review: N/A  
 candeleros y guardamancebos en posicion

IRC Rule 8.8 Change of ownership and/or changes in sail number will automatically invalidate the rating certificate.  
 IRC Rule 8.9 Physical changes which might affect the performance of the boat shall be declared and may invalidate the rating certificate  
 IRC Rule 13.4 It is a breach of the Rules of IRC for any owner or individual to intentionally supply false information.

**Seahorse** Magazine  
 Your free subscription:  
[www.seahorse.co.uk/digital](http://www.seahorse.co.uk/digital)  
 Passcode: 49917

**BARCO:**

Nombre: BRAMADOR  
 N° de vela: CHI6415  
 Tipo: FIRST 36.7 2.20  
 No. de Cert.: 39644  
 No. de tripulantes: 8 (680 kg)

**CERTIFICADO ESTANDAR**

Válido del: 22 Jan 26 11:55:02  
 Hasta el: 31 May 26

**CASCO**


LH 10.68  
 LWP 9.19  
 Peso: 5499  
 DLR 221  
 Calado : 2.21

**NOTAS - APAREJO Y VELA**

Energía manual para ajustar las jarcias de labor  
 El pie de mástil/estay de proa no ajustables en regata

Número de velas de proa: 2  
 Max number of flying headsails carried: 0  
 Spinnaker max embarcados: 2

Peso con colchonetas y baterías



Units in metres unless otherwise stated.  
 IRC Rule 13.3 The accuracy of the measurements supplied shall be the owner's responsibility.  
 The boat drawing is approximated based on IRC rated data, if there is an error please contact your rule authority.